

Hydraulic and Lubrication Interchangeable Element Range

Part Numbers

Note: Bold and darker tint panel indicates the item is standard and available to order immediately.

| Filter Element Competitor | Filter Element Competitor Part Number | Parker Part Number |
|---------------------------|---------------------------------------|--------------------|
| Eaton Vickers | Replaces VRF2B1C20 | 933116Q |
| Eaton Vickers | Replaces VRF2B2C03 | 932692Q |
| Eaton Vickers | Replaces VRF2B2C05 | 932693Q |
| Eaton Vickers | Replaces VRF2B2C10 | 932694Q |
| Eaton Vickers | Replaces VRF2B2C20 | 933117Q |
| Eaton Vickers | Replaces VRF2V1C03 | 932689Q |
| Eaton Vickers | Replaces VRF2V1C05 | 932690Q |
| Eaton Vickers | Replaces VRF2V1C10 | 932691Q |
| Eaton Vickers | Replaces VRF2V1C20 | 933118Q |
| Eaton Vickers | Replaces VRF2V2C03 | 932695Q |
| Eaton Vickers | Replaces VRF2V2C05 | 932696Q |
| Eaton Vickers | Replaces VRF2V2C10 | 932697Q |
| Eaton Vickers | Replaces VRF2V2C20 | 933119Q |
| Eppensteiner | Replaces 1.0145 H6SL-A-000-P | 936789Q |
| Eppensteiner | Replaces 1.561 H3SL-C-000-P(S) | 936736Q |
| Eppensteiner | Replaces 1.561 H6SL-A-000-P | 936869Q |
| Eppensteiner | Replaces 1.561 H6SL-C-000-P | 936816Q |
| Eppensteiner | Replaces 1-0145 H3SL-A-000-P | 936737Q |
| Eppensteiner | Replaces 2.0030 H6SL-A-000-P | 938155Q |
| Eppensteiner | Replaces 2.0030 H6SL-B00-0-P | 936784Q |
| Eppensteiner | Replaces 2.140H6SL-C-000-P | 936787Q |
| Eppensteiner | Replaces 2.22 H6SL-C-000-P | 936786Q |
| Eppensteiner | Replaces 2.56G2525-C-000-PS | 936785Q |
| Eppensteiner | Replaces 9.05242 P25-S00-0-PX | 944090Q |
| Filtration Products Corp | Replaces FPL1270B05G | 935202 |
| Filtration Products Corp | Replaces FPL1370B05G | 935210 |
| Filtration Products Corp | Replaces FPL2270B05G | 935206 |
| Filtration Products Corp | Replaces FPL2370B05G | 935214 |
| Fleetguard | Replaces HF7808 | 982131 |
| Fleetguard | Replaces HF7809 | 983061 |
| Hydac | Replaces 0015D010BN4HC | 938156Q |
| Hydac | Replaces 0030D003BH4HC | PR3035Q |
| Hydac | Replaces 0030D003BN4HC | PR3031Q |
| Hydac | Replaces 0030D005BH4HC | PR3036Q |
| Hydac | Replaces 0030D005BN4HC | PR3032Q |
| Hydac | Replaces 0030D010BH4HC | PR3037Q |
| Hydac | Replaces 0030D010BN4HC | PR3033Q |
| Hydac | Replaces 0030D020BH4HC | PR3038Q |
| Hydac | Replaces 0030D020BN4HC | PR3034Q |
| Hydac | Replaces 0030D025W | 939159Q |
| Hydac | Replaces 0030R003BN4HC | 938253Q |
| Hydac | Replaces 0030R005BN4HC | 938254Q |
| Hydac | Replaces 0030R010BN4HC | 938255Q |
| Hydac | Replaces 0030R020BN4HC | 938256Q |
| Hydac | Replaces 0035D020BN4HC | 937058Q |
| Hydac | Replaces 0060D003BH4HC | PR3064Q |
| Hydac | Replaces 0060D003BN4HC | PR3056Q |
| Hydac | Replaces 0060D005BH4HC | PR3065Q |
| Hydac | Replaces 0060D005BN4HC | PR3057Q |
| Hydac | Replaces 0060D010BH4HC | PR3066Q |
| Hydac | Replaces 0060D010BN4HC | PR3058Q |
| Hydac | Replaces 0060D020BH4HC | PR3067Q |
| Hydac | Replaces 0060D020BN4HC | PR3059Q |
| Hydac | Replaces 0060R003BN4HC | 938257Q |
| Hydac | Replaces 0060R005BN4HC | 938258Q |
| Hydac | Replaces 0060R010BN4HC | 938259Q |
| Hydac | Replaces 0060R020BN4HC | 938260Q |

| Filter Element Competitor | Filter Element Competitor Part Number | Parker Part Number |
|---------------------------|---------------------------------------|--------------------|
| Hydac | Replaces 0075R003BN4HC | 938261Q |
| Hydac | Replaces 0075R005BN4HC | 938262Q |
| Hydac | Replaces 0075R010BN4HC | 938263Q |
| Hydac | Replaces 0075R020BN4HC | 938264Q |
| Hydac | Replaces 0095D010BN4HC | 938154Q |
| Hydac | Replaces 0110D003BH4HC | PR3093Q |
| Hydac | Replaces 0110D003BN4HC | PR3085Q |
| Hydac | Replaces 0110D005BH4HC | PR3094Q |
| Hydac | Replaces 0110D005BN4HC | PR3086Q |
| Hydac | Replaces 0110D010BH4HC | PR3095Q |
| Hydac | Replaces 0110D010BN4HC | PR3087Q |
| Hydac | Replaces 0110D020BH4HC | PR3096Q |
| Hydac | Replaces 0110D020BN4HC | PR3088Q |
| Hydac | Replaces 0110R003BN4HC | 938265Q |
| Hydac | Replaces 0110R005BN4HC | 938266Q |
| Hydac | Replaces 0110R010BN4HC | 938267Q |
| Hydac | Replaces 0110R020BN4HC | 938268Q |
| Hydac | Replaces 0140D003BH4HC | 937059Q |
| Hydac | Replaces 0140D003BN4HC | 937060Q |
| Hydac | Replaces 0140D005BH4HC | 937061Q |
| Hydac | Replaces 0140D005BN4HC | 937062Q |
| Hydac | Replaces 0140D010BH4HC | 937063Q |
| Hydac | Replaces 0140D010BN4HC | 937064Q |
| Hydac | Replaces 0140D020BH4HC | 937065Q |
| Hydac | Replaces 0140D020BN4HC | 937066Q |
| Hydac | Replaces 0160D003BH4HC | PR3122Q |
| Hydac | Replaces 0160D003BN4HC | PR3114Q |
| Hydac | Replaces 0160D005BH4HC | PR3123Q |
| Hydac | Replaces 0160D005BN4HC | PR3115Q |
| Hydac | Replaces 0160D010BH4HC | PR3124Q |
| Hydac | Replaces 0160D010BN4HC | PR3116Q |
| Hydac | Replaces 0160D020BH4HC | PR3125Q |
| Hydac | Replaces 0160D020BN4HC | PR3117Q |
| Hydac | Replaces 0160R003BN4HC | 938269Q |
| Hydac | Replaces 0160R005BN4HC | 938270Q |
| Hydac | Replaces 0160R010BN4HC | 938271Q |
| Hydac | Replaces 0160R020BN4HC | 938272Q |
| Hydac | Replaces 0165R003BN4HC | 938273Q |
| Hydac | Replaces 0165R005BN4HC | 938274Q |
| Hydac | Replaces 0165R010BN4HC | 938275Q |
| Hydac | Replaces 0165R020BN4HC | 938276Q |
| Hydac | Replaces 0240D003BH4HC | PR3151Q |
| Hydac | Replaces 0240D003BN4HC | PR3143Q |
| Hydac | Replaces 0240D005BH4HC | PR3152Q |
| Hydac | Replaces 0240D005BN4HC | PR3144Q |
| Hydac | Replaces 0240D010BH4HC | PR3153Q |
| Hydac | Replaces 0240D010BN4HC | PR3145Q |
| Hydac | Replaces 0240D020BH4HC | PR3154Q |
| Hydac | Replaces 0240D020BN4HC | PR3146Q |
| Hydac | Replaces 0240D200WHC | 938195Q |
| Hydac | Replaces 0240R003BN4HC | 938277Q |
| Hydac | Replaces 0240R005BN4HC | 938278Q |
| Hydac | Replaces 0240R010BN4HC | 938279Q |
| Hydac | Replaces 0240R020BN4HC | 938280Q |
| Hydac | Replaces 0330D003BH4HC | PR3180Q |
| Hydac | Replaces 0330D003BN4HC | PR3172Q |
| Hydac | Replaces 0330D005BH4HC | PR3181Q |

Hydraulic and Lubrication Interchangeable Element Range



Part Numbers

Note: Bold and darker tint panel indicates the item is standard and available to order immediately.

| Filter Element Competitor | Filter Element Competitor Part Number | Parker Part Number |
|---------------------------|---------------------------------------|--------------------|
| Hydac | Replaces 0330D005BN4HC | PR3173Q |
| Hydac | Replaces 0330D010BH4HC | PR3182Q |
| Hydac | Replaces 0330D010BN4HC | PR3174Q |
| Hydac | Replaces 0330D020BH4HC | PR3183Q |
| Hydac | Replaces 0330D020BN4HC | PR3175Q |
| Hydac | Replaces 0330R003BN4HC | 938281Q |
| Hydac | Replaces 0330R005BN4HC | 938282Q |
| Hydac | Replaces 0330R010BN4HC | 938283Q |
| Hydac | Replaces 0330R020BN4HC | 938284Q |
| Hydac | Replaces 0480D003BH4HC | 937067Q |
| Hydac | Replaces 0480D003BN4HC | 937068Q |
| Hydac | Replaces 0480D005BH4HC | 937069Q |
| Hydac | Replaces 0480D005BN4HC | 937070Q |
| Hydac | Replaces 0480D010BH4HC | 937071Q |
| Hydac | Replaces 0480D010BN4HC | 937072Q |
| Hydac | Replaces 0480D020BH4HC | 937073Q |
| Hydac | Replaces 0480D020BN4HC | 937074Q |
| Hydac | Replaces 0480R003BN4HC | 944058Q |
| Hydac | Replaces 0480R005BN4HC | 944059Q |
| Hydac | Replaces 0480R010BN4HC | 944060Q |
| Hydac | Replaces 0480R020BN4HC | 944061Q |
| Hydac | Replaces 0500D003BH4HC | 937075Q |
| Hydac | Replaces 0500D003BN4HC | 937076Q |
| Hydac | Replaces 0500D005BH4HC | 937077Q |
| Hydac | Replaces 0500D005BN4HC | 937078Q |
| Hydac | Replaces 0500D010BH4HC | 937079Q |
| Hydac | Replaces 0500D010BN4HC | 937080Q |
| Hydac | Replaces 0500D020BH4HC | 937081Q |
| Hydac | Replaces 0500D020BN4HC | 937082Q |
| Hydac | Replaces 0500R003BN4HC | 938285Q |
| Hydac | Replaces 0500R005BN4HC | 938286Q |
| Hydac | Replaces 0500R010BN4HC | 938287Q |
| Hydac | Replaces 0500R020BN4HC | 938288Q |
| Hydac | Replaces 0660D003BH4HC | PR3209Q |
| Hydac | Replaces 0660D003BN4HC | PR3201Q |
| Hydac | Replaces 0660D005BH4HC | PR3210Q |
| Hydac | Replaces 0660D005BN4HC | PR3202Q |
| Hydac | Replaces 0660D010BH4HC | PR3211Q |
| Hydac | Replaces 0660D010BN4HC | PR3203Q |
| Hydac | Replaces 0660D020BH4HC | PR3212Q |
| Hydac | Replaces 0660D020BN4HC | PR3204Q |
| Hydac | Replaces 0660R003BN4HC | 938289Q |
| Hydac | Replaces 0660R005BN4HC | 938290Q |
| Hydac | Replaces 0660R010BN4HC | 938291Q |
| Hydac | Replaces 0660R020BN4HC | 938292Q |
| Hydac | Replaces 0850R003BN4HC | 938293Q |
| Hydac | Replaces 0850R005BN4HC | 938294Q |
| Hydac | Replaces 0850R010BN4HC | 938295Q |
| Hydac | Replaces 0850R020BN4HC | 938296Q |
| Hydac | Replaces 0950R003BN4HC | 938297Q |
| Hydac | Replaces 0950R005BN4HC | 938298Q |
| Hydac | Replaces 0950R010BN4HC | 938299Q |
| Hydac | Replaces 0950R020BN4HC | 938300Q |
| Hydac | Replaces 1300R003BN4HC | 938301Q |
| Hydac | Replaces 1300R005BN4HC | 938302Q |
| Hydac | Replaces 1300R010BN4HC | 938303Q |
| Hydac | Replaces 1300R020BN4HC | 938304Q |

| Filter Element Competitor | Filter Element Competitor Part Number | Parker Part Number |
|---------------------------|---------------------------------------|--------------------|
| Hydac | Replaces 1700R003BN4HC | 938305Q |
| Hydac | Replaces 1700R005BN4HC | 938306Q |
| Hydac | Replaces 1700R010BN4HC | 938307Q |
| Hydac | Replaces 1700R020BN4HC | 938308Q |
| Hydac | Replaces 2600R003BN4HC | 938310Q |
| Hydac | Replaces 2600R005BN4HC | 938311Q |
| Hydac | Replaces 2600R010BN4HC | 938312Q |
| Hydac | Replaces 2600R020BN4HC | 938313Q |
| Hydac | Replaces 0100RK010BN4HC | 944091Q |
| Hydac | Replaces 0100RK015BN4HC | 944092Q |
| Hydac | Replaces 1320D010BH4HC | 941693 |
| Internormen | Replaces 01.E 170.10VG.30.E.V | 938232Q |
| Internormen | Replaces 01.E 170.10VG.HR.E.V | 938172Q |
| Internormen | Replaces 01.E 170.25VG.30.E.V | 938233Q |
| Internormen | Replaces 01.E 170.25VG.HR.E.V | 938173Q |
| Internormen | Replaces 01.E 170.3VG.30.E.V | 938230Q |
| Internormen | Replaces 01.E 170.3VG.HR.E.V | 938170Q |
| Internormen | Replaces 01.E 170.6VG.30.E.V | 938231Q |
| Internormen | Replaces 01.E 170.6VG.HR.E.V | 938171Q |
| Internormen | Replaces 01.E 210.10VG.16.S.V | 938188Q |
| Internormen | Replaces 01.E 210.25VG.16.S.V | 938189Q |
| Internormen | Replaces 01.E 210.3VG.16.S.V | 938186Q |
| Internormen | Replaces 01.E 210.6VG.16.S.V | 938187Q |
| Internormen | Replaces 01.E 30.10VG.30.E.V | 938244Q |
| Internormen | Replaces 01.E 30.25VG.30.E.V | 938245Q |
| Internormen | Replaces 01.E 30.3VG.30.E.V | 938242Q |
| Internormen | Replaces 01.E 30.6VG.30.E.V | 938243Q |
| Internormen | Replaces 01.E 320.10VG.16.S.V | 938168Q |
| Internormen | Replaces 01.E 320.25VG.16.S.V | 938169Q |
| Internormen | Replaces 01.E 320.3VG.16.S.V | 938166Q |
| Internormen | Replaces 01.E 320.6VG.16.S.V | 938167Q |
| Internormen | Replaces 01.E 360.10VG.30.E.V | 938220Q |
| Internormen | Replaces 01.E 360.10VG.HR.E.V | 938176Q |
| Internormen | Replaces 01.E 360.25VG.30.E.V | 938221Q |
| Internormen | Replaces 01.E 360.25VG.HR.E.V | 938177Q |
| Internormen | Replaces 01.E 360.3VG.30.E.V | 938218Q |
| Internormen | Replaces 01.E 360.3VG.HR.E.V | 938174Q |
| Internormen | Replaces 01.E 360.6VG.30.E.V | 938219Q |
| Internormen | Replaces 01.E 360.6VG.HR.E.V | 938175Q |
| Internormen | Replaces 01.E 425.10VG.16.E.V | 938236Q |
| Internormen | Replaces 01.E 425.10VG.16.S.V | 938192Q |
| Internormen | Replaces 01.E 425.25VG.16.E.V | 938237Q |
| Internormen | Replaces 01.E 425.25VG.16.S.V | 938193Q |
| Internormen | Replaces 01.E 425.3VG.16.E.V | 938234Q |
| Internormen | Replaces 01.E 425.6VG.16.E.V | 938235Q |
| Internormen | Replaces 01.E 450.10VG.30.E.V | 938224Q |
| Internormen | Replaces 01.E 450.10VG.HR.E.V | 938216Q |
| Internormen | Replaces 01.E 450.25VG.30.E.V | 938225Q |
| Internormen | Replaces 01.E 450.25VG.HR.E.V | 938217Q |
| Internormen | Replaces 01.E 450.3VG.30.E.V | 938222Q |
| Internormen | Replaces 01.E 450.3VG.HR.E.V | 938214Q |
| Internormen | Replaces 01.E 450.6VG.30.E.V | 938223Q |
| Internormen | Replaces 01.E 450.6VG.HR.E.V | 938215Q |
| Internormen | Replaces 01.E 631.10VG.16.S.V | 938212Q |
| Internormen | Replaces 01.E 631.25VG.16.S.V | 938213Q |
| Internormen | Replaces 01.E 631.3VG.16.S.V | 938210Q |
| Internormen | Replaces 01.E 631.6VG.16.S.V | 938211Q |