


# Brass Adaptors


**0127**

Tube Support for Polymer Tubing



Brass



ØD1	ØD2		L	kg
4	2	<a href="#">0127 04 00</a>	11	0.001
	2.7	<a href="#">0127 04 27</a>	11	0.001
5	3	<a href="#">0127 05 03</a>	11	0.001
	3.3	<a href="#">0127 05 00</a>	11.5	0.009
6	4	<a href="#">0127 06 00</a>	11.5	0.001
8	5.5	<a href="#">0127 08 55</a>	14	0.001
	6	<a href="#">0127 08 00</a>	14	0.001
10	7	<a href="#">0127 10 07</a>	18	0.001
	7.5	<a href="#">0127 10 75</a>	18	0.001
	8	<a href="#">0127 10 00</a>	18	0.002
12	8	<a href="#">0127 12 08</a>	18	0.002
	9	<a href="#">0127 12 09</a>	18	0.002
14	10	<a href="#">0127 12 00</a>	18	0.001
	11	<a href="#">0127 14 11</a>	18	0.002
15	12	<a href="#">0127 14 00</a>	18	0.002
16	12	<a href="#">0127 15 12</a>	18	0.002
18	13	<a href="#">0127 16 13</a>	18	0.003
20	14	<a href="#">0127 18 14</a>	19.5	0.003
22	15	<a href="#">0127 20 15</a>	20.5	0.003
25	16	<a href="#">0127 22 16</a>	21	0.004
	19	<a href="#">0127 25 19</a>	25	0.007

This tube support guarantees good gripping, at high temperatures and pressures, by preventing collapsing of the tube.